



Test Report

Timber Testing Centre Reference 6-87-2020

Report Number 20200611-115637

Testing Status Contract

Samples Submitted 11/06/2020

Date of Issue 11/06/2020

Greg Muir
Sales Manager QLD
Borg Manufacturing Pty Ltd.
1090 Old Pacific Highway, Somersby, NSW, 2250, Australia

TESTING DETAILS

Test Method(s):

Samples have been tested in accordance with AS/NZS 4266.1.

Test Location:

Timber Testing Centre, Unit 2, 107 Northlink Place, Virginia, QLD, 4014

LIMITATIONS OF REPORT

All results reported apply only to the sample tested and apply to the sample as received by the Timber Testing Centre.

This report shall not be reproduced except in full.

Results do not extend to any other manufactured product or to ongoing manufactured products.

The Timber Testing Centre makes no claims to the ongoing ability of the manufacturer to meet required manufacturing standards.

The results of this report do not determine the compliance of the test material to any manufacturing standards.

Prior treatment, handling, conditioning and exposure and its effect on the sample prior to testing have not been verified.

This report shall not be reproduced or published by the customer without the written consent of the Timber Testing Centre.

TEST RESULTS

Number of samples submitted for testing: 1

Testing Period: 26/05/2020 through 11/06/2020

Sample ID	* Sample Description	Test Name	Test Result
6-87-1-20	Product Type: Particleboard Standard: AS/NZS 1859.1 Particleboard Panels Grade: Moisture Resistant Thickness: 9mm Manufactured Date: Not Provided	Panels Formaldehyde AS/NZS 4266.1 S17	Test Result: 1.04mg/L Std Dev: 0.00 Max Test Limit: 1.5mg/L

* Sample description information has been provided by the client

Additions/Deviations/Exclusions:

A cutting plan is not provided, samples were submitted pre-cut. The mean and standard deviation values reported apply to the results of replicate test pieces. One formaldehyde test has been performed, the duplicate pieces shall only be tested in the case of abnormal or failed results. The internal desiccator temperature check for formaldehyde testing has not been recorded.

SAMPLING DETAILS

The Timber Testing Centre did not conduct sampling. Samples were submitted to the Timber Testing Centre by the client.

Regards,



Suzie Steiger

Compliance Manager